

FIG. 1





FIG. 2






FIG. 4





FIG. 5







FIG. 8








FIG. 10




FIG. 11A




FIG. 11B




FIG. 11D




FIG. 11C




FIG. 12




FIG. 13A




FIG. 13B




FIG. 14A




FIG. 14B





FIG. 14C

FIG. 14D



FIG. 14F







FIG. 15

15/29

HYPOTHERMIC MOR ORGAN RECOVERY






FIG. 17




FIG. 17A




FIG. 18






FIG. 18A








FIG. 22







FIG. 23






FIG. 25

	OPERATION	SPEED	MOTOR DRIVE WAVEFORM	PRESSURE WAVEFORM
1	D.C.	CONSTANT	0	\sim
2	ACTIVE CONTINUOUS	SLOW		0
	ACTIVE CONTINUOUS	FAST	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	0
3	ACTIVE WAVEFORM AMPLITUDE MODULATING	SLOW <		
	ACTIVE WAVEFORM AMPLITUDE	FAST <		
4	ACTIVE WAVEFORM PULSE WIDTH	SLOW -		
	MODULATING ACTIVE WAVEFORM PULSE WIDTH MODULATING	FAST -		<u> </u>

FIG. 25A




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31